

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
		"322"/\$.ccls. and (mosfet mos) near12 switch\$3 near12 near12 (field near3 winding coil)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:11
L1	2	"318"/\$.ccls. and (field near10 (sensor detect\$4)) near24 (torque near12 (measur\$3 calculat\$3)) AND (output near7 current near10 (sensor detect\$3)) near24 (torque near12 (measur\$3 calculat\$3)) AND ((rotation rpm) near7 (sensor detect\$3)) same (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:27
L2	1	"322"/\$.ccls. and (field near10 (sensor detect\$4)) near24 (torque near12 (measur\$3 calculat\$3)) AND (output near7 current near10 (sensor detect\$3)) near24 (torque near12 (measur\$3 calculat\$3)) AND ((rotation rpm) near7 (sensor detect\$3)) same (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:33
L3	0	"180"/\$.ccls. and (field near10 (sensor detect\$4)) near24 (torque near12 (measur\$3 calculat\$3)) AND (output near7 current near10 (sensor detect\$3)) near24 (torque near12 (measur\$3 calculat\$3)) AND ((rotation rpm) near7 (sensor detect\$3)) same (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:28
L4	0	"323"/\$.ccls. and (field near10 (sensor detect\$4)) near24 (torque near12 (measur\$3 calculat\$3)) AND (output near7 current near10 (sensor detect\$3)) near24 (torque near12 (measur\$3 calculat\$3)) AND ((rotation rpm) near7 (sensor detect\$3)) same (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:28
L5	5	(field near10 (sensor detect\$4)) near24 (torque near12 (measur\$3 calculat\$3)) AND (output near7 current near10 (sensor detect\$3)) near24 (torque near12 (measur\$3 calculat\$3)) AND ((rotation rpm) near7 (sensor detect\$3)) same (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:23

L6	1	"322"/\$.ccls. and (field near10 (sensor detect\$4)) near24 (torque near12 (measur\$3 calculat\$3)) AND (output near7 current near10 (sensor detect\$3)) near24 (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:33
L7	3	"322"/\$.ccls. and (field near10 (sensor detect\$4)) near24 (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:36
L8	1	"180"/\$.ccls. and (field near10 (sensor detect\$4)) near24 (torque near12 (measur\$3 calculat\$3)) AND (output near7 current near10 (sensor detect\$3)) near24 (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:33
L9	4	"322"/\$.ccls. and ((field near10 (coil winding current) near12 (sensor detect\$4))) near24 (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 12:49
L10	3	(denso).as. and ((field near10 (coil winding current) near12 (sensor detect\$4))) near24 (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:44
L11	2	(honda).as. and ((field near10 (coil winding current) near12 (sensor detect\$4))) near24 (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 10:31
L13	713	322/19.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:55
L17	0	ho02p 09/00.ipc.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 10:26

L18	1	ho02p 009/00.ipc.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 10:27
L19	77470	h02p 009/00.ipc.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 10:27
L20	2	19 and ((field near10 (coil winding current) near12 (sensor detect\$4))) near24 (torque near12 (measur\$3 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 10:42
L21	3	19 and ((field near10 (coil winding current) near12 (sensor detect\$4))) near24 (torque near12 (measur\$3 determi\$4 estimat\$4 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 10:47
L22	0	"323"/\$.ccls. and ((field near10 (coil winding current) near12 (sensor detect\$4))) near24 (torque near12 (measur\$3 determi\$4 estimat\$4 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 10:47
L23	4	"322"/\$.ccls. and ((field near10 (coil winding current) near12 (sensor detect\$4))) near24 (torque near12 (measur\$3 determi\$4 estimat\$4 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 10:47
L24	97	((field near10 (coil winding current) near12 (sensor detect\$4))) near24 (torque near12 (measur\$3 determi\$4 estimat\$4 calculat\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 12:47
L25	548	322/29.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 12:28
L26	0	24 and (on off) near12 (voltage current) near12 (coil winding) near12 ratio	USPAT	OR	ON	2005/07/12 13:18

L27	5	"322"/\$.ccls. and (mosfet mos) near12 switch\$3 near12 detect\$3 near12 current	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:03
L28	40	"323"/\$.ccls. and (mosfet mos) near12 switch\$3 near12 detect\$3 near12 current	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:05
L29	44	"363"/\$.ccls. and (mosfet mos) near12 switch\$3 near12 detect\$3 near12 current	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:03
L30	43	"361"/\$.ccls. and (mosfet mos) near12 switch\$3 near12 detect\$3 near12 current	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:03
L31	8	"323"/\$.ccls. and (mosfet mos) near12 switch\$3 near12 detect\$3 near12 current near12 (field winding coil)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:09
L32	9	"363"/\$.ccls. and (mosfet mos) near12 switch\$3 near12 detect\$3 near12 current near12 (field winding coil)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:11
L33	44	"322"/\$.ccls. and (mosfet mos) near12 switch\$3 near12 (field near3 winding coil)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:12
L34	6	24 and armature near24 (rpm rotation\$e rotat\$3)	USPAT	OR	ON	2005/07/12 13:19
L35	435	((rotation rotational rotor rpm) near7 (sensor detect\$3)) same (frequenc\$3 near12 (current voltage power) near12 (armature winding))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:30

L36	38	"322"/\$.ccls. and ((rotation rotational rotor rpm) near7 (sensor detect\$3)) same (frequenc\$3 near12 (current voltage power) near12 (armature winding))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 13:30
S1	543	(makoto near3 taniguchi).in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 13:41
S2	65452	(denso).as.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 13:42
S3	16	S1 and (field near10 (sensor detect\$4)) and (output near7 current near10 (sensor detect\$3)) and ((rotation rpm) near7 (sensor detect\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 13:58
S4	26	S2 and (field near10 (sensor detect\$4)) and (output near7 current near10 (sensor detect\$3)) and ((rotation rpm) near7 (sensor detect\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 14:43
S5	381	322/20.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:55
S6	675	322/24.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 14:41
S7	58	322/26.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 14:41

S8	3541	322/28.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 12:28
S9	2	"322"/\$.ccls. and (field near10 (sensor detect\$4)) and (output near7 current near10 (sensor detect\$3)) and ((rotation rpm) near7 (sensor detect\$3)) same torque near12 (measur\$3 calculat\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 14:45
S10	0	"323"/\$.ccls. and (field near10 (sensor detect\$4)) and (output near7 current near10 (sensor detect\$3)) and ((rotation rpm) near7 (sensor detect\$3)) same torque near12 (measur\$3 calculat\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 14:45
S11	0	"307"/\$.ccls. and (field near10 (sensor detect\$4)) and (output near7 current near10 (sensor detect\$3)) and ((rotation rpm) near7 (sensor detect\$3)) same torque near12 (measur\$3 calculat\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 14:45
S12	0	"363"/\$.ccls. and (field near10 (sensor detect\$4)) and (output near7 current near10 (sensor detect\$3)) and ((rotation rpm) near7 (sensor detect\$3)) same torque near12 (measur\$3 calculat\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 14:45
S13	4	"318"/\$.ccls. and (field near10 (sensor detect\$4)) and (output near7 current near10 (sensor detect\$3)) and ((rotation rpm) near7 (sensor detect\$3)) same torque near12 (measur\$3 calculat\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/12 09:07
S14	2	"180"/\$.ccls. and (field near10 (sensor detect\$4)) and (output near7 current near10 (sensor detect\$3)) and ((rotation rpm) near7 (sensor detect\$3)) same torque near12 (measur\$3 calculat\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 14:45

S15	0	"280"/\$.ccls. and (field near10 (sensor detect\$4)) and (output near7 current near10 (sensor detect\$3)) and ((rotation rpm) near7 (sensor detect\$3)) same torque near12 (measur\$3 calculat\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 14:45
S16	704	290/54.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/11 15:02
S17	424	290/54.ccls.	USPAT	OR	OFF	2005/07/11 15:05
S18	115	"322"/\$.ccls. and power near3 system and current near3 transformer and switch\$2	USPAT	OR	ON	2005/07/11 15:05